



PRESS RELEASE – June 10, 2015

Communications: 972-624-3156

Repair work underway at South Colony/Paige

THE COLONY, Texas — Public Works crews began roadwork this morning at the intersection of South Colony Boulevard and Paige Road to repair a portion of the street that has buckled due to thermal expansion.

Public Works Director Leo Lavender said thermal expansion can occur when a roadway gets too hot, too fast, which is understandable considering the weather has gone from mild temperatures and rain to 90-degree days in a short period of time.

The work is taking place in the eastbound lanes on the east side of the intersection. One lane will remain open to traffic.

Motorists are strongly encouraged to observe signage and slow down, as the buckling has created an incline in the road.

Repairs to both eastbound lanes are estimated to be completed and open to traffic by July 3.



For information, contact Director of Government Relations Brant Shallenburger at 972-624-3108, bshallenburger@thecolonytx.gov.

###